

**Agenda of 3<sup>rd</sup> Special Meeting on Metering issues in NER**

**Date: 21.03.2015**

**Time: 1300 Hrs.**

**Venue: State Guest House, Agartala.**

**Follow-up items:**

1. Distribution of 35 SEMs and 10 DCDs already procured : Status report
2. Urgent procurement of 50 SEMs and 10 DCDs on Single Tender basis as approved in 24<sup>th</sup> CCM : ***NERTS may kindly intimate the status***

On procurement of these meters, meters should be there at all locations as identified by NERLDC. Further, meters should be replaced in all locations where there are errors.

***NERTS may kindly intimate the status.***

3. Procurement of 250 SEMs / 40 Laptops / 20 DCDs : Status
4. Time drift in meters : ***Status and action taken by Constituents in last one month***
5. Error in meter reading : It was decided that POWERGRID NERTS will attend following at the earliest :
  - 132 KV Balipara-Gohpur line : Meter error in Balipara end
  - 132 kV Imphal-Ningthoukong (very low reading at Ningthoukong end)
  - 132 kV Nirjuli-Gohpur (Low reading at Nirjuli end)
  - 220 kV Kathalguri – Tinsukia II (Tinsukia end reading <50%)

***NERTS may kindly intimate the status.***

6. AMR scheme was agreed in principle by 24<sup>th</sup>. Commercial Committee. It is necessary to expedite the AMR project for smooth collection of SEM reading. NERTS may intimate status.

***NERTS may kindly intimate the status***

## New Items:

1. Erratic behaviour of ELSTER make meters.
2. Erratic behaviour of ELSTER make meters. NTPC has reported erratic readings of SEM located on Line -2 of 400 kV NTPC - Bongaigaon.
3. 132 KV Agia-Nangalbibra line: Meter reading less than half at Nangalbibra end.
4. Action plan for replacement of SEMs with large time drift (on receipt of 50 SEMs being procured on single tender basis).
5. Installation of check meters in ISGS (in phased manner on receipt of 50 SEMs being procured on single tender basis).
6. Furnishing Meter installation report: It is observed that installation report of SEM is not furnished to NERLDC/NERPC in time resulting in problems in computation. ***NERTS may be advised to furnish installation report with details of CTR, PTR immediately after installation.***

\*\*\*\*\*